

run clear port-security sticky interface

The **run clear port-security sticky interface** command clears the sticky secure MAC addresses of a secure interface.

Command Syntax

run clear port-security sticky interface {all | gigabit-ethernet <interface-name> [vlan <vlan-id>]}

Parameter

Parameter	Description
interface {all gigabit-ethernet <interface-name>}	Specifies the physical interface name. The value could all or a specific interface name.
vlan <vlan-id>	Optional. Specifies a VLAN. The value is an integer that ranges from 1 to 4094.

Example

- Run the command **run clear port-security sticky interface** to clear the sticky secure MAC addresses of ge-1/1/33.

```
admin@Xorplus# run clear port-security sticky interface gigabit-ethernet ge-1/1/33
Clear done.
```