

# interface gigabit-ethernet <port> wred queue <value> min\_thresh

---

Users can set minimum thresh.

## Command Syntax

```
set interface gigabit-ethernet <port> wred queue <value> min_thresh <int>
delete interface gigabit-ethernet <port> wred queue <value> min_thresh
```

## Parameter

- <port> ethernet switching port identifier, the valid ports range 1-52
- <value> The queue number, [0..7]
- <int> The threshold identifier, [0..8000]

## Example

- This example sets max thresh for ge-1/1/3:

```
admin@XorPlus# set interface gigabit-ethernet ge-1/1/3 wred queue 2 min_thresh 1
admin@XorPlus# commit
```