

# set interface ethernet-switching-options port-error-discard timeout

The **set interface ethernet-switching-options port-error-discard timeout** command configures the port recovery interval when the port security violation mode is **shutdown-temp**.

## Command Syntax

**set interface ethernet-switching-options port-error-discard timeout** *<seconds>*

## Parameter

Parameter	Description
<b>timeout</b> <i>&lt;seconds&gt;</i>	Specifies the port recovery interval when the port security violation mode is <b>shutdown-temp</b> . The value is an integer, in seconds, that ranges from 10 to 300.  The default value is 20 seconds.

## Example

- Configure the port recovery interval when the port security violation mode is shutdown-temp.

```
admin@XorPlus# set interface ethernet-switching-options port-error-discard timeout 10
admin@XorPlus#commit
```