

run clear port-security port-error

When the port security violation mode is **shutdown**, the port will be set to the *error-discard* state when detecting a violation. User can recover the port with the **run clear port-security port-error** command.

Command Syntax

run clear port-security port-error interface {all | gigabit-ethernet <interface-name>}

Parameter

Parameter	Description
interface {all gigabit-ethernet <interface-name>}	Specifies the physical interface name.

Example

- Run the command **run clear port-security port-error** to recover the port ge-1/1/33.

```
admin@Xorplus# run clear port-security port-error interface gigabit-ethernet ge-1/1/33
Clear done.
```